# Outgross CO150018

# **Suzanne Steab - April 2011 inspection Reports**

From:

Karl Houskeeper

To:

Dennis.Oakley@PacifiCorp.com; Ken.Fleck@PacifiCorp.com

Date:

5/4/2011 3:26 PM

Subject:

April 2011 inspection Reports

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments:

Deer Creek April 2011.pdf; Deer Creek Independent OSM April 2011.pdf; Deer Creek February

2011.pdf

Dennis/Ken,

Attached is the April 2011 inspection report for Deer Creek, the OSM Independent Partial Oversite Inspection done in April, and the February 2011 inspection report that you requested an additional copy of.

Thanks, Karl



# State of Utah

#### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representativ	os Present During the Inspection:
Company	Guy Davis
OGM	Kari Houskeeper
Secretaria de la como de deservo de deservo.	THE RESERVE OF THE PROPERTY OF

# **Inspection Report**

Permit Number:	C0150018
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, April 13, 2011
Start Date/Time:	4/13/2011 11:00:00 AM
End Date/Time:	4/13/2011 2:00:00 PM
Last Inspection:	Tuesday, March 08, 2011

Inspector: Karl Houskeeper. Weather: Clear, Temp. 55 Deg. F. InspectionID Report Number: 2714

Accepted by: jhelfric

Permitee: ENERGY WEST MINING CO Operator: ENERGY WEST MINING CO

Site: DEER CREEK MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current	Acreages

19,740.78	<b>Total Permitted</b>
98.05	<b>Total Disturbed</b>
0.60	Phase I
	Phase II
	Phase III

### Mineral Ownership

#### **Types of Operations** ✓ Federal ✓ Underground ✓ State Surface Loadout County ✓ Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl R. Lousbuper

Wednesday, Ap

Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Wednesday, April 13, 2011

Page 2 of 3

# REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  b. For PARTIAL inspections check only the elements evaluated.
  Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
  Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
  Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	1.1			
2.	Signs and Markers	<b>y</b>		<b>y</b>	[ ]
3.	Topsoil			******	
4.a	Hydrologic Balance: Diversions	V.		Y	-
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	7			
4.c	Hydrologic Balance: Other Sediment Control Measures				["]
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations			F11 12	
5.	Explosives		["]		
6.	Disposal of Excess Spoil, Fills, Benches		1		1000
7.	Coal Mine Waste, Refuse Piles, Impoundments	["]	P207		
8.	Noncoal Waste		2 18		
9.	Protection of Fish, Wildlife and Related Environmental Issues	CJ.	;j	[]	
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	111	ing \$		
13.	Revegetation				(7)
14.	Subsidence Control		2 mar si		
15.	Cessation of Operations	1	i i i i i i i i i i i i i i i i i i i	1	
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls		,		
17.	Other Transportation Facilities			()	IJ
18.	Support Facilities, Utility Installations		Part Ann.		
19.	AVS Check			1777	
20.	Air Quality Permit	11.00	70000 1		
21.	Bonding and Insurance				
22.	Other	7****	*****	1	

Inspection Continuation Sheet

Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Wednesday, April 13, 2011

Page 3 of 3

# 2. Signs and Markers

The mine identifications signs are located at the various points of access into the permit areas. The signs are current with the required information.

### 4.a Hydrologic Balance: Diversions

Culvert replacement is taking place along side of the C1 conveyor where the access road to the sediment pond takes off from the county road. The operator notified the Division in advance of this maintenance work.



# State of Utah

#### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

#### Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representativ	es Present During the Inspection:
OSM	Elizabeth Shaeffer
OGM	Karl Houskeeper
Company	Dennis Oakley

# **Inspection Report**

Permit Number:	C0150018
Inspection Type:	IND PART OVERSITE
Inspection Date:	Wednesday, April 27, 2011
Start Date/Time:	4/27/2011 10:00:00 AM
End Date/Time:	4/27/2011 3:00:00 PM
Last Inspection:	Thursday, April 14, 2011

Inspector: Karl Houskeeper,

Weather: <u>Partly Cloudy, Temp. 47 Deg. F.</u> InspectionID Report Number: <u>2723</u>

Accepted by: jhelfric

5/3/2011

Permitee: **ENERGY WEST MINING CO**Operator: **ENERGY WEST MINING CO** 

Site: DEER CREEK MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

	Current Acreages		Mineral Ownership Type:		s of Operations	
Г	19,740.78	<b>Total Permitted</b>	<b>✓</b> Federal	$\mathbf{Z}$	Underground	
	98.05	Total Disturbed	✓ State		Surface	
	0.60	Phase I	☐ County		Loadout	
		Phase II	<b>∀</b> Fee		Processing	
		Phase III	Other		Reprocessing	

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl Houskeeper,

Inspector ID Number: 49

Date

Wednesday, App

OIL, GAS & MINIF

Permit Number: C0150018

Inspection Type: IND PART OVERSITE Inspection Date: Wednesday, April 27, 2011

Page 2 of 3

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  For PARTIAL inspections check only the elements evaluated.
  Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
  Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
  Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale			()	[]
2.	Signs and Markers	V	O	Z	
3.	Topsoil			[7]	
4.a	Hydrologic Balance: Diversions	V		~	[]
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V	[]	~	[1]
4.c	Hydrologic Balance: Other Sediment Control Measures	<b>D</b>		100	
4.d	Hydrologic Balance: Water Monitoring		Ö		
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches			T D	
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		<b>V</b>	
8.	Noncoal Waste	Y		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	F***			
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading			L	0
13.	Revegetation		(1)		
14.	Subsidence Control	[7]			(***)
15.	Cessation of Operations		[1]	Ü	
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls			]	Pass
17.	Other Transportation Facilities		Para An		
18.	Support Facilities, Utility Installations	V		Y	(I)
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance	D.	IJ		
22.	Other		[1]		

Page 3 of 3

#### 2. Signs and Markers

Mine identification signs were observed at the Waste Rock Site, Main Facilities and at Rilda Facilities. All three signs contained the required information.

#### 4.a Hydrologic Balance: Diversions

A culvert inlet along side of the access road to the Rilda Pad has tumble weeds in front of the opening. The weeds need to be removed to prevent a substantial blockage.

#### 4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds at the Waste Rock Site, Main Facility and Rilda Facility were viewed during the inspection. The Main Facility sediment pond is the only pond that contained water. All ponds appeared stable.

#### 7. Coal Mine Waste, Refuse Piles, Impoundments

It appears as if new material has been placed on cell a or the northern cell. The cell from the last certified inspection was nearing its designed capacity. The pile will need to be surveyed to determine if it is now at capacity. The refuse pile appeared stable. No visible hazards were observed.

#### 8. Noncoal Waste

Noncoal waste was observed in various locations at the Main Facility. The locations ranged from the access road, storage areas, parking area, portal area, the diversion and three inlets on the incline of the road into the parking area. This has been an area of concern in the past and has been cited numerous times. The trash needs to be gathered and disposed of properly. Elizabeth Shaeffer noted that the approved noncoal waste storage area is less than desirable and probably adds to the constant and reoccurring noncoal waste problems. No action was taken at this time but future infractions will need to be addressed by enforcement action.

#### 18. Support Facilities, Utility Installations

Sections of the corrugated metal cover over the conveyor belt line have come loose and are laying on the ground. They were observed at approximately inverted U #52 on the C2 belt line (Offside) and adjacent to the C1 belt line toward the inlet side of the sediment pond (Roadside).



# State of Utah

#### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

#### Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

### epresentatives Present During the Inspection Company Dennis Oakley OGM Karl Houskeeper

# **Inspection Report**

Permit Number:	C0150018
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, February 02, 2011
Start Date/Time:	2/2/2011 8:30:00 AM
End Date/Time:	2/2/2011 1:00:00 PM
Last Inspection:	Thursday January 06 2011

Inspector: Karl Houskeeper. Weather: Clear, Temp. 5 Deg. F. InspectionID Report Number: 2637

> Accepted by: jhelfric 2/3/2011

Permitee: ENERGY WEST MINING CO Operator: ENERGY WEST MINING CO

Site: DEER CREEK MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

	Current Acreages		Mineral Ownersi	пір Тур	Types of Operations		
1	9,740.78	Total Permitted	☑ Federal	V	Underground		
	98.05	Total Disturbed	<b>✓</b> State		Surface		
	0.60	Phase I	County		Loadout		
		Phase II	✓ Fee		Processing		
		Phase III	Other	О	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Date

Wednesday, F

Karl Houskeeper,

Inspector ID Number: 49

Note/59ใหญ่ เละสุดิธรรษการิการ์ เลยสาย เลยสาย เลยสาย เลยสาย เลยสาย เลยสาย เลยสาย (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • พายนะ ogm.utah.gov

Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Wednesday, February 02, 2011

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  For PARTIAL inspections check only the elements evaluated.
  Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
  Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
  Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale		Eli	[	1
2.	Signs and Markers	Υ.	F1 =1	V	1)
3.	Topsoil	5)		13	
4.a	Hydrologic Balance: Diversions	<b>y</b>	Ð	¥	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>y</b>		0	)
4.c	Hydrologic Balance: Other Sediment Control Measures	[]	L)	D	
4.d	Hydrologic Balance: Water Monitoring		(***)		
4.e	Hydrologic Balance: Effluent Limitations		,	[7]	
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches			[]	
7.	Coal Mine Waste, Refuse Piles, Impoundments		, a house		
8.	Noncoal Waste	Ý		О	
9.	Protection of Fish, Wildlife and Related Environmental Issues			2747 Mg	
10.	Slides and Other Damage			[7]	, min
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control	13		13	
15.	Cessation of Operations			177	
16.a	Roads: Construction, Maintenance, Surfacing				, ,
16.b	Roads: Drainage Controls	(1)	P** 1.	Ö	
17.	Other Transportation Facilities	[1]			
18.	Support Facilities, Utility Installations	53			
19.	AVS Check				[
20.	Air Quality Permit	,			# · · · · · · · · · · · · · · · · · · ·
21.	Bonding and Insurance			4 th to 14	
22.	Other		Name of		

Permit Number: C0150018

Inspection Continuation Sheet

Inspection Type: PARTIAL

Inspection Date: Wednesday, February 02, 2011

Page 3 of 3

## 2. Signs and Markers

Mine identification signs at the waste rock site, main facility and rilda facility are all placed at points of public access into the permit area.

## 4.a Hydrologic Balance: Diversions

Diversions are snow covered.